

TST200

1-wire transmitter for Pt100 temperature sensor, 2-3-4 wire sensor, -200 - +850°C, cascade coupling FEATURES

1-wire communication - 2 x RJ11 connectors for daisy chain connection
2 - 3 - 4 wire Pt100 temperature sensor - 4 wire is recommended.
Built-in A/D converter with compensation
24 bit resolution for temperature measurement
Calibrated digital output
Excellent long-term stability
Each sensor has its own unique 64 bit serial number

