

Pt100 transmitter - 2 or 3 wire, 4-20mA output.
Temperature from -50 to +200°C with adjustment
potentiometers. 24VDC

FEATURES

- Pt100 transmitter from sensor to 4-20mA
- Working voltage: 24VDC
- Accuracy: +/- 0.2% full scale
- Temperature range: -50 - +200°C
- Dimensions: Ø45 mm
- Plastic
- Weight: 25g
- Clamping: Center hole
- Zero point adjustment
- Adjustment of amplitude

