

Temperature and humidity sensor -20 to + 80 ° C, 0 to 90% rH, 1 x mini-DIN, 2.3m cable. Accessories for GUDE

## FEATURES

Temperature sensor +/- 0.5 ° C, humidity +/- 3%,  
Sensor is automatically detected by equipment  
Length: 2.3 m with Mini-DIN connector  
Accessories for: GUDE NPOWER , GUDE PDUs,  
Remote Control

