

PT100-F-3

3-wire PT 100 sensor in metal housing $\varnothing 5 \times 50$ mm, -
50 - +100°C, 3 meter cable

FEATURES

- 3 wire PT 100 sensor
- 100 ohms at 20°C
- With 1 compensation cable (yellow)
- Metal housing $\varnothing 5 \times 50$ mm
- 304 stainless steel
- 3 meter cable
- Temperature range: - 50 - +100°C

